NOVA PORTAFOLIO

POSSIBILITIES ARE ENDLESS AS WE BUILT TO LAST





WHAT WE DO?

ROOFING AND WATERPROOFING SYSTEMS

Roof Replacement Roof Recovery Slate Roof Replacement Balcony and terrace waterproofing Façade walls waterproofing

FAÇADE RESTORATION

Masonry Restoration Local law 11 Repairs Metal panel Systems Stucco Installation Façade and Stone Cleaning

ARCHITECTURAL METALS

Cast Iron Repair and Replacement
Cornice Restoration and Replacement
Canopy, Entrance and Gate Restoration
Dormer Restoration
Copper Roof Replacement
Skylight Replacement
Fire escape restoration
Steel Restoration and Replacement
Window Restoration
Railing Replacement
Structural Shoring

ARCHITECTURAL STONE

Landmark Preservation
Terra Cotta Repair and Replacement
Limestone, Brownstone and Granite
Repair and Replacement

ACCESS

Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist

CONCRETE & COATING

Sidewalk Replacement
Cast Stone Installation
GFRC/GFRP Cornice restoration
Coating Repair and Installation
Vault Repairs and Replacement
Concrete Eyebrow and Structural repairs

CONSULTING

Emergency Repairs
Aearial Lift Inspections
Suspended Scaffolding Inspection
Mortar and Stone Analysis
Test Cleaning and Sampling
Roofing Analysis
Leak Investigation
Color Matching



TABLE OF CONTENTS

118-21 Queens Blvd 131 Duane Street 141 East 88th Street 150 Central Park South 150 Central Park South 20 West 44 Street Balustrade Restoration 20 West 44th Street 2211 Broadway- Sidewalk Vault Rehabilitation 378 West End Avenue - Masonry Restoration 410 Riverside Drive 505 LaGuardia Pl "564 Park Avenue (Phase A + Phase B)" 66 Morton Street 940 Park Avenue, NY 451 Broome Street 2211 Broadway 108 Leonard Street 660 Park Ave. 924 West End Avenue 35 Crosby Street Saint Mark's Church in the Bowery / 131 East 10th Street 830 Park Avenue 840 Park Avenue 205 West 89th Street 2 East 70th Street The Players Club - The Lucy G. Moses Preservation Awards -2014 - 16 Gramercy Park Suth 440 Riverside Drive 15 West 67th Street 129 West 22nd Street 1035 Park Avenue Pratt Family Mausoleum Locust Valley Box Hill 34 Gramercy Park East 59 Bleecker Street 65 Bleecker Street St. Paul's Chapel 11-13 East 67th Street



16 West 16th Street 700 Park Ave



1181-21 QUEENS BLVD 2019-2022

Exterior repairs. Parapet Asbestos abatement coping, base flashing, roofing strip. Brick masonry replacement. Roof Drain Replacement. Roof Drain Replacement. Chimney repairs. Cutting & pointing.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs Metal panel Systems

Access Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist

Architectural Metals

Window Restoration







131 Duane Street **2020 - 2022**

Marble Facade Restoration: units replacements, paint striping of marble surfaces, crack repairs, brackets replacement. Dutchman repairs. Mortar restoration. Brick restoration: masonry replacement, cracks fill. Sheet Metal cornice replacement.

SERVICE

Façade Restoration

Masonry Restoration Façade and Stone Cleaning

Architectural Metals


Cornice Restoration and Replacement Fire escape restoration

Architectural Stone

Landmark Preservation Limestone, Brownstone and Granite Repair and Replacement



Sciame Construction LLC





141 East 88th Street2020 - Ongoing

Local Law 11 inspections. Terra Cotta Repair and Replacement. Parapet wall replacement. Roof replacement. Leak Investigation. Metal Panels System. Window replacement. GFRP cornice fabrication and installation

SERVICE

Roofing and Waterproofing Systems

Roof Replacement Balcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs Metal panel Systems

Architectural Metals

Steel Restoration and Replacement Window Restoration

Architectural Stones

Terra Cotta Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist

Concrete & Coating

GFRC/GFRP Cornice restoration



Lawless & Mangione, Architects & Engineers, LLP





150 Central Park South 2018 - 2019

Rebuild exisiting window openings. Replacement all exisiting shel angle, new waterproofing system installation.

SERVICE

Façade Restoration Masonry Restoration Local law 11 Repairs

Access Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist

Architectural Metals

Steel Restoration and Replacement

Concrete & Coating GFRC/GFRP Cornice restoration



Sciame Construction LLC





HEMPSHIRE HOUSE

150 Central Park South 2020 - Ongoing

Removal of exsiting sidewalk shed and installation of heavy duty sidewalk shed. Pipe Scaffold Installation. Brick removal and installation of new. Brick corner removal. Waterproofing. Door Lintel Replacement. Window rebricking. Parapet Wall Demoilition.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs

Access

Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist

Architectural Metals Steel Restoration and Replacement

Concrete & Coating

GFRC/GFRP Cornice restoration



Bertolini Architectural Work, D.P.C.





THE GENERAL **SOCIETY OF MECHANICS & TRADESMEN GSMT**

20 West 44 Street **Balustrade Restoration** 2019 - 2021



Masonry Repointing & Caulking. Ornamental Metals. Sheet Metal Flashing and Trim. Fire Escpae Restorationt

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs Façade and Stone Cleaning

Architectural MetalsCornice Restoration and Replacement
Fire escape restoration

Architectural Stone


Landmark Preservation
Terra Cotta Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding



Easton Architects, LLP






THE GENERAL SOCIETY OF MECHANICS & TRADESMEN GSMT

20 West 44th Street

2021 - Ongoing



SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs Façade and Stone Cleaning

Architectural Metals

Cornice Restoration and Replacement Fire escape restoration

Architectural Stone


Landmark Preservation Terra Cotta Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding



Howard L. Zimmerman Architects. P.C.





2211 Broadway- Sidewalk Vault Rehabilitation

2019 - Ongoing

Sidewalk concrete pavement removal and installation. Granite Slabs removal and reinstallation. Metal Gate removal and reinstallation. Stone Railing removal and reisntallation. Roof Drains, Trench Drains, New Steel Framing Dutchman repairs, brick replacement. Brick Repointing.

SERVICE

Architectural Metals

Canopy, Entrance and Gate Restoration

Architectural Stone


Landmark Preservation

Concrete & Coating

Vault Repairs and Replacement



Vidaris, Inc.





378 West End Avenue -**Masonry** Restoration 2020 - 2022

Brick Masonry Replacement and re-pointing. Limestone and Dutchman repaors. Structural steel repair, waterproofing. Repoint of limestone ornamentation. Terra-Cotta Reaplacement: furnish and install new units. Terra-Cotta steel lintel replacement at Window Heads, removal of cracked terra-cotta stones to reveal steel lintels. Scrape, prime and painting of exposed window lintels and 3rd Floor Balcony Guards. Sealant replacement.Furnish New GFRC banister with bracket (with weeps at the sealant joint) and balustrade. Furnish and install Hanover pavers. Install new aluminium railing. Reconstruction historic cresting on West and North facade. Remove and discard window at light wells on the West and North facade. Facade Brick Cleaning - West and North Facade. Facade Limestone

SERVICE

Façade Restoration

Cleaning Base.

Masonry Restoration Local law 11 Repairs Facade and Stone Cleaning

Architectural Stone


Landmark Preservation Terra Cotta Repair and Replacement Limestone, Brownstone and Granite Repair and Replacement

Concrete & Coating

Cast Stone Installation GFRC/GFRP Cornice restoration



Leeding Builders Group LLC





410 Riverside Drive

2019 - 2022

Facade Repairs. Granite Stone repointing, patch repairs, Dutchman repair. Masonry Repairs: repointing at Roman Brick Masonry, Roman brick replacement, Limestone Reppointing and Staple Adhesive, Pin Adhesive repair. Terra-Cotta Repairs: patching, glaze coating application, staple repair, crack repairs, architectural terra-cotta block replacement, corner quoin replacement. Corner Stabllization. Window Sealant Replacement. Miscellaneous Facade Repairs.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Fire escape restoration

Architectural Stone


Landmark Preservation Terra Cotta Repair and Replacement Limestone, Brownstone and Granite Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding
Suspended Scaffolding Material Hoist



CANY Architecture & Engineering D.P.C





505 LaGuardia Pl

2019 - 2022

Sidewalk Shed Installation and Removal. Scaffolding. Asbestos Removal. Sounding of Concrete. Concrete Repairs. Sealant Replacement. Concrete Repairs. Replacement and Repairs of Reinforcing Bars.

SERVICE

Façade Restoration

Local law 11 Repairs

Architectural Stone

Landmark Preservation

Concrete & Coating

Concrete Eyebrow and Structural repairs







COLONY CLUB

564 Park Avenue **2019 - 2021**

Remove and replace all white glazed brick on facades, including bulkhead at the main roof. Remove and replace masonry to facilitate steel repairs and replacement face brick. Remove and replace exisiting marble coping stones. Remove and replace exisiting bluestone and cast stone window sills. Remove and rebuild existing parapet walls. Extend existing parapet wall at upper roof north and west facades. Remove and replace existing water table stones. Remove and replace existing window sills with new cast stone window sills. Repair crack and install expansion joint. Remove, restore and reinstall existing iron fence at west parapet wall. Provide and install new specified shelf angles. Reinforce deteriorated structural steel members exposed at all areas. Provide and install specified flashing and trim at window heads, sills and copings. Provide and install self-adhered flashing at window and door lintels and jambs at each opening. Provide and install vapor permeable air and water barrier membrane to parged backup masonry. Fully parge backup masonry as substrate for air and water barrier frames new specified fire-rated windows and frames to match existing. Remove and replace existing roof system. Relocate as required and reinstall existing electrical conduit, condensate pipes, and surface mounted lighting to facilitate brick replacement. Relocate existing refrigerant pipes as required to perform masonry work. Extend height of pipes as required due to parapet wall alternation and reinstall include draining and filling of pipes.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Canopy, Entrance and Gate Restoration. Skylight Replacement

Architectural Stone

Landmark Preservation



Howard L. Zimmerman Atchitects. P.C.





66 Morton Street

2020 - Ongoing

Exterior and interior scaffolding. Temporary Roof. Demolition. Salvage. New Masonry. Masonry Restoration. Cast Stone and stucco. Cornice outrigger and restoration. Roofing membrane. Flashings. Flat Seam Roof. Furnish and installtion of skylights. Rebuild the top of the parapet to the wood lintels above the windows. Furnish and install angle brackets at the interior connection of the West and North Facade. Fabrication and installation of new bluestone units.

SERVICE

Roofing and Waterproofing Systems Roof Replacement

Façade Restoration

Masonry Restoration Stucco Installation Façade and Stone Cleaning

Architectural Metals

Copper Roof Replacement Skylight Replacement

Architectural Stone


Limestone, Brownstone and Granite Repair and Replacement

Concrete & Coating

Cast Stone Installation



Sweeney + Conroy, Inc.





940 Park Avenue, NY

2017 - 2018



Brick and masonry repairs. Lintel replacement and repairs. Terra cotta restoration. Natural stone repair. Stucco replacement. Terra-Cotta parapet repairs.

SERVICE

Roofing and Waterproofing Systems Balcony and terrace waterproofing

Façade Restoration Masonry Restoration Local law 11 Repairs

Architectural Stones

Landmark Preservation Terra Cotta Repair and Replacement Limestone, Brownstone and Granite Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding Suspended Scaffolding Material Hoist



Bertolini Architectural Work, D.P.C..





451 Broome **Street**

2017 - 2018

Facade restoration. Lintel reconstruction and repairs. Terra cotta replacement. Limestone repairs. Cornice repairs. Face brick replacement.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals
Cast Iron Repair and Replacement
Cornice Restoration and Replacement
Fire escape restoration
Window Restoration

Architectural Stones

Landmark Preservation Terra Cotta Repair and Replacement

Access Sidewalk shed Pipe Scaffolding Suspended Scaffolding









THE APTHORP

2211 Broadway 2017 - 2018

Skylight replacement, Roof Replacement with new sipast system, restoration of copper cornice, bulkhead repairs, iinstallation of new pavres.


SERVICE

Roofing and Waterproofing Systems Roof Replacement

Façade Restoration Metal panel Systems

Architectural Metals Cornice Restoration and Replacement Skylight Replacement







108 Leonard Street

2016 - 2018

Originally designed by McKim, Mead & White as the original home of the New York Life Insurance Company, 108 Leonard was constructed in two phases, during the years 1894–1904. It is a designated New York City Landmark, and is listed on the National Register of Historic Places. The landmark designation includes the Italian Renaissance Revival-style exterior.

Facade restoration including new cast stone parapet wall, installation of new balustrades 6 different types, bronze railing refurbishment, tones each) by usage of special engineering hoists, waterproofing of watertables with SIKA.

SERVICE

Roofing and Waterproofing Systems

Balcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs Façade and Stone Cleaning

Architectural Metals

Cast Iron Repair and Replacement Canopy, Entrance and Gate Restoration Railing Replacement

Architectural Stone


Limestone, Brownstone and Granite Repair and Replacement Landmark Preservation Terra Cotta Repair and Replacement

Concrete & Coating

Cast Stone Installation



New Line Structures





660 **Park Avenue**

2016 - 2018

Exterior restoration, cleaning of façade with Rotex Vortex system, facade repairs, limestone cleaning, window painitng, brick chimney reconstruction.

SERVICE

Roofing and Waterproofing Systems

Roof Replacement

Façade Restoration Masonry Restoration Local law 11 Repairs Façade and Stone Cleaning

Architectural Metals

Canopy, Entrance and Gate Restoration Fire escape restoration Window Restoration

Architectural Stones


Landmark Preservation Limestone, Brownstone nd Granite Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding



Joshep K. Blum Co. LLP





924 West End Avenue 2016 - 2017

Exterior repairs and balcony replacement with new cast corners, facade brick replacement, limestone replacement, stone replacement.

SERVICE

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Canopy, Entrance and Gate Restoration

Architectural Stones

Landmark Preservation Terra Cotta Repair and Replacement

Access


Sidewalk shed Suspended Scaffolding

Concrete & Coating

Cornice restoration



Joshep K. Blum Co. LLP





35 Crosby Street

2015 - 2017

Front wall reconstruction and exterior restoration. Cornice restoration. Reconstruction of brick masonry wall. Parapet reconstruction. Chimney reconstruction and repair.

SERVICE

Roofing and Waterproofing Systems

Roof Replacement

Façade RestorationMasonry Restoration
Façade and Stone Cleaning

Architectural Metals

Canopy, Entrance and Gate Restoration Cornice Restoration and Replacement Canopy, Entrance and Gate Restoration Fire escape restoration Steel Restoration and Replacement Window Restoration Structural Shoring

Architectural Stones

Landmark Preservation Limestone, Brownstone nd Granite Repair and Replacement

Access

Sidewalk shed Pipe Scaffolding



Thomas A. Fenniman Architect.





Saint Mark's Church in the Bowery / **131 East** 10th Street

2016 - 2017



SERVICE

Architectural Metals Cast Iron Repair and

Replacement Canopy, Entrance and Gate Restoration Railing Replacement

Architectural Stone

Landmark Preservation Limestone, Brownstone and Granite Repair and Replacement





830 **Park Avenue**

2014 - 2015

Parapet wall replacement. Pointing. Removal and replacement of terra cotta. Terra cotta patching. Lintel replacement. Brick replacement. Courtyard roof replacement. Terra cotta and limestone sounding. Window repair.

SERVICE

Roofing and Waterproofing SystemsBalcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Skylight Replacement

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement

Access

Sidewalk shed Suspended Scaffolding



Lawless & Mangione, **Architects & Engineers, LLP**





840 **Park Avenue**

2014 - 2015

Replacement of lintels, waterproofing, installation of new cap flashing and extensiion of waterproofing between windows.

SERVICE

Roofing and Waterproofing Systems Roof Recovery

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement


Access Suspended Scaffolding

Concrete & Coating

Cast Stone Installation



Lawless & Mangione, **Architects & Engineers, LLP**







ASTOUR COURT

205 West 89th Street 2013 - 2015

Terrace reconstruction. West terrace greenhouse flashings, fence. Terrace two main roof replacement, including new quarry tiles, new wood lattice fencing, new copper corner at bulkhead, new railings at

SERVICE


Roofing and Waterproofing Systems

Balcony and terrace waterproofing

Architectural MetalsCornice Restoration and Replacement



Walter B. Melvin **Architects, LLC**







SERVICE

Roofing and Waterproofing Systems Roof Recover Balcony and terrace waterproofing


Façade Restoration Masonry Restoration

Architectural Stone

Limestone, Brownstone and Granite Repair and Replacement



Walter B. Melvin **Architects, LLC**





The Players Club -The Lucy G. Moses Preservation Awards 2014
16 Gramercy Park Suth

2012 - 2015

Restoring and renewing our historic landmark and sustaining it for the future. Replacement of two floors of brownstone entrance, including new columns, restoration of railing, cornice and facade.

SERVICE

Façade Restoration Façade and Stone Cleaning

Architectural Metals Cast Iron Repair and Replacement Cornice Restoration and Replacement Canopy, Entrance and Gate Restoration
Window Restoration
Railing Replacement
Structural Shoring

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement



Thomas A. Fenniman, **Architect**





440 Riverside Drive 2013 - 2014



SERVICE

Roofing and Waterproofing Systems

Roof Replacement Balcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs Metal panel Systems

Architectural Metals

Cornice Restoration and Replacement Skylight Replacement

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement

Concrete & Coating

Cast Stone Installation GFRC/GFRP Cornice restoration



Zaskorski & **Notaro Architects** AIA,LLP





Replacement of 2 floors of vertical columns hilding up two floors with interior protection of the apartment on the inside, rebuiliding of parapets with extensive steel repairs, 100% repointing of steel elevation, replacement of east and west large fire escape, installation of new roofing system at all roofs including new bluestone pavers at common terrace with new aluminium railings.

SERVICE

Roofing and Waterproofing Systems

Roof Replacement Balcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Fire escape restoration Steel Restoration and Replacement Railing Replacement Structural Shoring

Architectural Stone

Landmark Preservation Limestone, Brownstone and Granite Repair and Replacement



Walter B. Melvin **Architects, LLC**







SERVICE

Roofing and Waterproofing Systems Roof Replacement Balcony and terrace waterproofing

Architectural MetalsSteel Restoration and Replacement
Structural Shoring



Thomas A. Fenniman, **Architect**







Recontruction of terra cotta paraptes with cast stone, face brick replacement, cutting and pointing, terrace replacement, reconstruction of balcony balustrade.

SERVICE

Roofing and Waterproofing Systems

Roof Replacement Balcony and terrace waterproofing

Façade Restoration Masonry Restoration Local law 11 Repairs

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement


Concrete & Coating

Cast Stone Installation



Joshep K. Blum Co. LLP





Pratt Family Mausoleum **Locust Valley**

2005 - 2006

Removal and reinstallation of 30 granite mausoleum roof stones (weight up to 30,000 pounds each). And exterior stone, replacement of part of the roof stone, pointing, cleaning of exterior walls

SERVICE

Architectural StoneLimestone, Brownstone and
Granite Repair and Replacement

Façade Restoration Façade and Stone Cleaning









Roof replacement, flashing reglet installation, chimney cap flashing installation, wood shingles replacement.

SERVICE

Roofing and Waterproofing Systems Roof Replacement

Architectural Metals
Cornice Restoration and Replacement
Dormer Restoration



Mr. Daniel W. White151.



[Gramercy Neighborhood Associates Historic Preservation Award reconstruction, brick replacement, chimney reconstruction, cutting and pointing, slate roof repair, bluestone lintel and sill reconstruction, sidewalk reconstruction.

SERVICE

Façade Restoration

Masonry Restoration

Architectural Metals

Fire escape restoration

Architectural Stone

Landmark Preservation Limestone, Brownstone and Granite Repair and Replacement









59 Bleecker Street

2018 - 2020

cotta cutting, pointing, glazing.

SERVICE

Roofing and Waterproofing Systems Balcony and terrace waterproofing

Façade RestorationFaçade and Stone Cleaning

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement



Westerman **Construction Co, Inc.**





65 Bleecker Street 2012 - 2013

Parapet reconstruction, steel repairs, main roof replacement, bulkhead roof replacement, new skylight, bulkhead cladding, new bulkhead stucco, terra cotta cornice repairs, lintel replacement, new

SERVICE

Architectural Stone

Landmark Preservation Terra Cotta Repair and Replacement



Walter B. Melvin **Architects, LLC**







Replacement of 8,000 sqf of lead coated cooper. Salvaging and repairing of decorative copper. Clock restoration. Cleaning stone. Coating: removal at stone, metal, wood, plaster. Dutchman repair. Solder repair. Capital restoration. Louver restoration.

SERVICE

Architectural Metals

Cornice Restoration and Replacement Copper Roof Replacement Window Restoration

Architectural Stone

Landmark Preservation Limestone, Brownstone and Granite Repair and Replacement

Access


Sidewalk shed Pipe Scaffolding



SuperStructures







SERVICE

Roofing and Waterproofing Systems

Roof Replacement

Façade Restoration

Masonry Restoration Façade and Stone Cleaning

Architectural Metals


Dormer Restoration Copper Roof Replacement

Architectural Stone


Limestone, Brownstone and Granite Repair and Replacement



Peter Pennoyer Architects







SERVICE

Roofing and Waterproofing Systems Roof Replacement



Thomas A. Fenniman, **Architects**





Façade reskinning, roof replacement project

SERVICE

Roofing and Waterproofing Systems

Roof Replacement Balcony and terrace waterproofing

Façade Restoration

Masonry Restoration Local law 11 Repairs

Architectural Metals

Window Restoration Railing Replacement

Access

Sidewalk shed Pipe Scaffolding









estimating@novaconstructionservices.com 75 Kent Street, Brooklyn NY 11222 T. 718 349 7770 - 718 349 1099